

MaxFlight

C O R P O R A T I O N

MaxFlight Corporation
750 Airport Road
Lakehurst, NJ 08701-5507 USA

1 (732) 842-8898
fax +1 (732) 842-1114
www.maxflight.com

SERVICE BULLETIN

To: _____
Fax: _____
Company: _____
Subject: **MaxFlight Safety Service Bulletin 2000-09**
Sent: 4/13/00 at 8:30:00 PM

From: Rich Mascolo
Fax: +1 (732) 842-1114
Voice: +1 (732) 842-9898 235
Pages: 1 (including cover)

MESSAGE

Units Affected: All MaxFlight Simulators [VR2000, VR2002, VR2500 and MT3000]

Purpose: To ensure security of both Pitch and Roll Encoders

Action/Requirement: URGENT - SAFETY Bulletin

Instructions to comply with this SAFETY Bulletin:

- Locate the two set screws on the pitch encoder collar, remove and re-install using Blue Loctite and ensure that the screws are tightened firmly.
- Locate the one set screw on the roll motor encoder shaft collar, remove and re-install using Blue Loctite and ensure that the screw is tightened firmly.

We have made it a weekly requirement to inspect both encoders for security and set screws for tightness. Please add this requirement to your present weekly inspection.

IMPORTANT!

Please CONFIRM RECEIPT of this Service Bulletin by faxing this cover page with your signature to MaxFlight Corporation at +1 (732) 842-1114 within 2 days

Signature (confirming receipt)

URGENT