



WISDOM INDUSTRIES, INC



ALADIN BULLETIN

DATE: MARCH 1997
RIDE: ALADIN
SUBJECT: ALADIN TURNTABLE HINGES

On one ALADIN turntable, cracks have been discovered in the pipe sleeve on the outside turntable wing hinges.

Inspect the four outside turntable wing hinges for cracks in the area indicated on the drawing.

Perform the inspection when the wings are lowered. Visual, dye penetrant, or magnaflux inspection can be used.

If cracks are showing, contact Wisdom Industries for instructions on replacement of the hinge components.

Perform the visual inspection on a monthly basis.

If you no longer own this ride, please contact us so we can update our records.

Thank you for your cooperation in this matter. If you have any questions about this bulletin, please feel free to contact us at 1-800-634-6097 or 1-970-522-7515.