



NUMBER: B400R1054-0

DATE: Jan. 19, 1990

SERVICE BULLETIN

Effective Serial Numbers: All Units

Ride: GIANT GONDOLA WHEEL

Subject: Tie Rod Installation

CHANCE RIDES, INC. has received a report of a GIANT GONDOLA WHEEL ride which was operated without first installing the long tie rods and torsion rods. This could have resulted in serious structural damage to the ride and possible injury to passengers and bystanders.

NEVER OPERATE THE RIDE WITHOUT THE TIE RODS AND TORSION RODS PROPERLY INSTALLED.

Always install these parts exactly as described in the set-up portion of the CHANCE OPERATION & MAINTENANCE MANUAL. The tie rods and torsion rods are necessary to maintain the correct shape and alignment of the wheel. All maintenance and set-up personnel must be instructed as to the importance of these parts and their proper installation.

